

From: [Cole Walker](#)
To: [Marlo Berg](#)
Cc: [John Womack](#)
Subject: FW: THM samples
Date: Thursday, October 22, 2015 2:37:10 PM

Marlo,

Please see John Womack's response below.

Thanks,
Cole

From: John Womack
Sent: Tuesday, October 13, 2015 2:00 PM
To: Cole Walker <cwalker@crmwd.org>
Subject: RE: THM samples

Hi Marlo,

Here are our responses to your questions concerning the THM samples.

1. The samples have been taken on the 42" Moss Creek pipeline approximately 2.4 miles downstream of the RWPF injection point at an air valve location.
2. The samples taken up to September 2015 were of the old 80/20 blend ratio. This would have diluted the RWPF product water 1 to 4 parts Moss Creek water which may have made the THMs difficult to detect. From September forward the blend ratio will be 50/50. It will be interesting to see if any are detected with the new blend ratio.

Also to be noted, all samples have been taken only if the plant has been running for 4 or more hours so as to have an accurate composite sample.

Let me know if you have any questions or concerns.

Thank You

John W.

John Womack
System Operations Manager
Colorado River Municipal Water District
P.O. Box 869
Big Spring, TX 79720

Phone: (432) 267-6341
Fax: (432) 268-1196
jwomack@crmwd.org

From: Cole Walker
Sent: Friday, October 9, 2015 11:12 AM
To: John Womack <jwomack@crmwd.org>
Subject: FW: THM samples

From: Marlo Berg [<mailto:Marlo.Berg@tceq.texas.gov>]
Sent: Monday, October 5, 2015 11:32 AM
To: John Burch <jburch@crmwd.org>; Robert Hildreth <rhildreth@crmwd.org>; Cole Walker <cwalker@crmwd.org>
Cc: Craig Stowell <Craig.Stowell@tceq.texas.gov>
Subject: THM samples

Cole,

Thank you for taking sending us the reports THM reports. I have a few questions about them.

1. Where exactly did you take the sample?
2. I was looking at the TCEQ collected samples (see attached) and even with a blend, it seems that some THMs should be detected with the levels found in the TCEQ collected samples. Were you running at a very low blend? What do you think caused this disparity?

Thank you,

Marlo

Marlo Wanielista Berg, P.E. | Technical Review and Oversight Team | TCEQ
12100 Park 35 Circle, Bldg. F | Austin, Texas 78753 | 📞 (512) 239-6967 Fax: (512) 239-6050 | ✉️:
Marlo.Berg@tceq.texas.gov